

## OPTICAL BELT SCALE

- is easy to install
- is easy to calibrate
- is not affected by external factors (heat, cold, sunlight, dust, humidity)
- is reliable
- has no wear or moving parts (load cells etc.)
- is maintenance-free
- is a high-quality and innovative product with the ability to record, monitor and control the production output



Our optical belt scale is also not only a simple measuring system, it is also a tool to optimize the production profitably. Through the printed job log can be determined accurately when the plant is working, all the pauses and stops are recorded in order to get an **all-over time & production control** (which is important to indicate and avoid expensive downtime).

**Applications:** Coal, Minerals, Aggregates, Cement, Wood chips, Lime sludge, Bagasse, Fertilizer,, Sponge iron Etc.